

Important:

When filling out forms on the

# Massachusetts Department of Environmental Protection Bureau of Resource Protection - Wetlands WPA Form 8A – Request for Certificate of Compliance

DEP File Number:

300-0959 Provided by DEP

Massachusetts Wetlands Protection Act M.G.L. c. 131, §40

### A. Project Information

computer, use only the tab key to move your cursor - do not use the return key.	2.	Name 3111 Mailing Big F City/To (774) Phone This Paqu Applic
		5/22/ Dated
Upon completion of the work authorized in an Order of Conditions, the property owner must request a Certificate of Compliance from the issuing authority stating	3.	The p 9 Hol Street Parco Asses The f Banjo Proper
that the work or portion of the work has been satisfactorily		Worc Count

completed.

1.	This request is being made by:					
	Banjo Boy LLC					
	Name					
	31113 Hollerich Drive					
	Mailing Address					
	Big Pine Key	FL	33043			
	City/Town	State	Zip Code			
	(774) 264-9750					
	Phone Number					
2.	This request is in reference to work regulated by a final Order of Conditions issued to:					
	Paquette Builders					
	Applicant					
	5/22/2017	300-0959	300-0959			
	Dated	DEP File Number	DEP File Number			
3.	The project site is located at:					
	9 Holland Road	Sturbridge				
	Street Address	City/Town	City/Town			
	Parcel ID: 348-02338-009					
	Assessors Map/Plat Number	Parcel/Lot Number	Parcel/Lot Number			
4.	The final Order of Conditions was recorded at the Registry of Deeds for:					
	Banjo Boy LLC					
	Property Owner (if different)					
	Worcester	44044	384			
	County	Book	Page			
	Certificate (if registered land)					
5.	This request is for certification that (check one):					
	the work regulated by the above-referenced Order of Conditions has been satisfactorily completed.					
	the following portions of the work regulated by the above-referenced Order of Conditions have been satisfactorily completed (use additional paper if necessary).					

the above-referenced Order of Conditions has lapsed and is therefore no longer valid, and the work regulated by it was never started.



Massachusetts Department of Environmental Protection Bureau of Resource Protection - Wetlands WPA Form 8A – Request for Certificate of Compliance

DEP File Number:

300-0959 Provided by DEP

## Massachusetts Wetlands Protection Act M.G.L. c. 131, §40

### A. Project Information (cont.)

- 6. Did the Order of Conditions for this project, or the portion of the project subject to this request, contain an approval of any plans stamped by a registered professional engineer, architect, landscape architect, or land surveyor?
  - Yes If yes, attach a written statement by such a professional certifying substantial compliance with the plans and describing what deviation, if any, exists from the plans approved in the Order.

🛛 No

#### **B. Submittal Requirements**

Requests for Certificates of Compliance should be directed to the issuing authority that issued the final Order of Conditions (OOC). If the project received an OOC from the Conservation Commission, submit this request to that Commission. If the project was issued a Superseding Order of Conditions or was the subject of an Adjudicatory Hearing Final Decision, submit this request to the appropriate DEP Regional Office (see <a href="http://www.mass.gov/eea/agencies/massdep/about/contacts/find-the-massdep-regional-office-for-your-city-or-town.html">http://www.mass.gov/eea/agencies/massdep/about/contacts/find-the-massdep-regional-office-for-your-city-or-town.html</a>).

EBT Environmental Consultants, Inc. **GLENN E. KREVOSKY, CONSULTANT** 601 Main Street

North Oxford, MA 01537

glenn.krevosky@charter.net

Cell: (508)769-3659 Office: (508)987-0979

November 30, 2023

Sturbridge Conservation Commission 301 Main Street Sturbridge, MA 01566

Re. 9 Holland Road, Sturbridge – Request to Lift of Enforcement Order, dated 10/30/2019

Dear Commission,

The applicant, Richard DiBonaventura of Banjo Boy LLC, through their representative, EBT Environmental Consultants Inc., is requesting the enforcement order for 9 Holland Road be lifted. Twenty-three saplings were planted (listed below) on 5/21/2021 to replace the unpermitted trees cut as agreed upon a the Sturbridge Conservation Commission meeting on 2/2/2021. The forest is growing back at 595 Main Street (Blackington LLC) where a portion of the clearing took place. All work outlined on the Repair and Clean-Up plan dated 4/10/2016 has been completed.

- (5) Red Maple (2" To 2.5" Caliper)
- (6) Swamp White Oak (2" To 2.5" Caliper) •
- (5) Northern Red Oak (2" To 2.5" Caliper)
- (6) Black Gum Tupelo (2" To 2.5" Caliper)
- (1) White Oak (2" To 2.5" Caliper)

One of the issues with the site when EBT, Inc became involved was erosion across 9 Holland into the Quinebaug River caused by concentrated runoff from the DOTs clogged catch basins on Route 20. We have been working with DOT over the last few years and they have now filed a Notice of Intent (DEP File #300-1175) to install twin drop inlet catch basins which will handle the flow from Route 20, attenuate the colloidals and nutrient in the flow and then discharge the water to the Quinebaug River – a rare muscle habitat.

Respectfully,

<u>Glenn E. Hewely</u> Glenn E. Krevosky, consultant



Photo 1 taken by EBT, Inc. on 7/19/2023 – Looking west showing the stable entrance off of Route 20 downgradient of DOTs twin catch basins (the subject of stormwater overflow). The applicant has been keeping the catch basin grates clear of debris so Route 20's stormwater does not flush through 9 Holland and cause sedimentation into the Quinebaug River (as had been occurring prior to EBT, Inc's involvement in the project in 2019).



Photo 2 taken by EBT, Inc. on 7/19/2023 – Looking west with the mill structure behind the photo taker to the east showing a stable herbaceous layer within the yard. All yard areas surrounding the mill structures are stable.




Photo 3 taken by Richard Connelly on 10/6/2023 – 23 saplings were planted on 5/21/2021, as required by the Commission. The photo shows a typical example of the vigor of all of the saplings.



Photo 4 taken by EBT, Inc. on 7/16/2022 – Standing on the eastern property boundary of 9 Holland Road looking into the Blackinton LLC (595 Main Street) property where the forest undergrowth saplings and bushes have grown back from the original violation cutting, which occurred in 2019.