



510 Stafford Street
Charlton, MA 01507
508-248-2085
www.sbsewer.com

October 23, 2023

To whom it may concern,

Our findings upon running the camera through the SAS at 125 Mashapaug Rd, Sturbridge, MA on October 20th, 2023, are as follows: the system components are in good working order. The SAS is working as per design. The technician ran the camera and inspected the distribution box and found no evidence of the liquid level ever being high. The leach lines were dry with little residual effluent. No staining or indication of liquid level ever being high. The septic tank was pumped by us July 15th, 2022, no issues were noted at that time. Inspector saw no issues at time of service 10/20/23.

Thank you,

Stephanie Collins

Slims & Berthiaume Sewer Service, Inc.

510 Stafford Street | Charlton, MA 01507

508-248-2085 | www.sbsewer.com

stephanie@sbsewer.com

